



1 Church Appearance in 1860's.



2 Church after the floor was raised in 1930.



3 Raised again for a new foundation in 1951.



4 Appearance in Summer 2010.



5 Deconstruction begins 10/18/2010.



6 Covered porches removed 10/19/2010.



7 Block steps removed 10/23/2010.



8 Contractor begins dismantling 1/10/2011.



9 Roof trusses and front siding removed 1/14/2011.



10 Side walls and cross beams removed 1/18/2011.



11 Upper walls removed 1/20/2011.



12 Dismantling completed 1/21/2011.